



Hammonds Model AC800-1L-1L-1M Injection System Manual


NOTE: MARK STROKE SETTING BEFORE REMOVING ANY PART



1




2




3

*WARNING... FAILURE TO TORQUE SCREWS PROPERLY TO 40 IN. LBS. WILL REDUCE PUMP HEAD PERFORMANCE, RESULTING IN INSUFFICIENT INJECTION RATIO.




4



NOTE: AFTER THIS PROCEDURE IS COMPLETE, YOU MUST RECALIBRATE THE INJECTOR TO YOUR SPECIFICATIONS.

5



FOR TECHNICAL ASSISTANCE CALL HAMMONDS TECH. SVS. (281) 999-2900

HAMMONDS TECHNICAL SERVICES, INC.

SCALE NTS	APPROVED PART NUMBER	DRAWN BY SS
DATE 02/26/2009		REVISED -
DRAWING TITLE	"M" DIAPHRAGM REPLACEMENT	
HEAVY DUTY PUMP SERIES	DRAWING NUMBER	1460-1

DRAWING	LEVELS	VIEW
1460	10, 11	1