

PumpUp REPAIR KIT

Model 2P10 Heavy
Duty

Old injectors run like new!

PART NO:
HDAL-2P10-KIT-A


Upgrade injectors to factory specifications

FOR TECHNICAL ASSISTANCE CALL
Hammonds Technical Services
(800) 582-4224

PUMP FRAME
NOT INCLUDED IN KIT

-KIT CONTENTS-

ITEM NO.	PART NO.	QTY.	DESCRIPTION
1	101001	2	Stroke Adjustment Knob
2	101037	2	Screw, #10-32 x 1 1/2"
3	101005	2	Stroke Adjustment Cam
4	101152	4	Slide Bearing
5	101006	2	Crosshead
6	101007	4	Return Spring
7	101537	2	O-Ring, AFLAS
	101839	2	O-Ring, Viton (Opt)
8	881908	2	Seal, Lip
9	882949	2	Plunger, P10
10	101539	1	Lubriplate 3/8 Ounce






HAMMONDS TECHNICAL SERVICES

"P" PLUNGER Pump Service

—Inspection and Replacement—


FOR TECHNICAL ASSISTANCE CALL (281) 999-2900

1 "P" PLUNGER PUMP SERVICE*




*Typical for Any Size Plunger Pump


2 INSPECT PLUNGER




3 REMOVE PLUNGER



4 REPLACE PLUNGER



5 REPLACE SEALS



6 RE-ASSEMBLY

