


PumpUp REPAIR KIT

Model 2P15 HD Heavy Duty
PART NO: HDAL-2P15-KIT-A
Old injectors run like new!

Upgrade injectors to factory specifications

FOR TECHNICAL ASSISTANCE CALL
Hammonds Technical Services
(800) 582-4224

PUMP FRAME
NOT INCLUDED IN KIT



-KIT CONTENTS-

ITEM NO.	PART NO.	QTY.	DESCRIPTION
1	102300-02	2	Back-Up Ring
2	881046	2	Setscrew, 1/4-20 x 1 (Part of #3)
3	102200	2	Plunger, P15
4	103583	2	Spring, Compression
5	883342	2	Seal Lip
6	102302	2	Sleeve, Teflon
7	103521	2	O-Ring, AFLAS
8	101001	2	Stroke Adjustment Knob
9	101037	2	Screw, 10-32 x 1 1/2"
10	101005	2	Stroke Adjustment Cam
11	101152	4	Slide Bearing
12	101007	4	Return Spring
13	101539	1	Lubriplate 3/8 Ounce



HAMMONDS TECHNICAL SERVICES, INC.

6807 West Little York • Houston, Texas 77040 • (800) 582-4224
www.hammondscos.com